How do I become a REAC Certified UPCS Inspector?

Introduction

All HUD assisted and insured housing (MF and Public Housing) covered under the Department's Uniform Physical Condition Standards (UPCS) regulations must be inspected by individuals certified in the Department's UPCS inspection protocol and procedures. The Physical Assessment Sub System (PASS) of the Office of Public and Indian Housing - Real Estate Assessment Center (PIH-REAC) facilitates these inspections. The information below explains how to become a certified UPCS inspector.

Procedures

The following 14 steps describe how to become a certified UPCS inspector.

Step	Who Does It	What Happens
1	Potential training participant	Accesses and reads the Physical
		Inspection web page
		(http://www.hud.gov/offices/reac/products/pr
		odpass.cfm) to get information about
		training, assessment questionnaire,
		Inspector Administration and Quality
		Assurance
2	Potential training participant	Electronically submits the Inspector
		Candidate Assessment Questionnaire via
		email to:
		inspector_assessment_form@hud.gov
3	PIH-REAC (UPCS	Reviews information from potential
	Inspection Training Team)	training participant to determine whether
		or not the individual meets the training
		qualifications.
4	Qualified Inspector	Receives and reviews congratulatory
	Candidate	email from UPCS Inspection Training
		Team. If desired, submits training request
		in appropriate format, to the Training
		Team via email:
		reac_pass_regstr@hud.gov
5	PIH-REAC (UPCS	Receives request and confirms
	Inspection Training Team)	availability of training session requested
		by trainee. Provides trainee with training
		materials and software via website.
6	Qualified Inspector	Provides verifiable documentation to
	Candidate	PIH-REAC, certifying their Inspector
		Candidate Assessment Questionnaire
		submitted information

7	PIH-REAC (UPCS	Reviews verifiable documentation for
/	Inspection Training Team)	completeness. Confirms proper
	inspection training ream)	install/download of inspection software.
		Sends Final Confirmation via email to
0	O1:6-1 It	Qualified Inspector Candidate
8	Qualified Inspector	Training Phase I: Attends 5 day training
	Candidate	session, participates fully, and passes all
0	DHI DEAG (I	tests. 100% attendance is mandatory.
9	PIH-REAC (Inspector	Once Certification Training Phase I is
	Administration)	successfully passed, provides inspector
		photo id badge and "M" id number
10	Conditionally Certified	Receives a REAC Inspection assignment
	UPCS Inspector	by either winning a bid and awarded an
		inspection assignment on the Reverse
		Auction Website and/or receives
		inspection assignment directly from a
		Servicing Mortgagee (or an inspection
		company providing the Servicing
		Mortgagees that service).
11	PIH-REAC (Quality	Phase II Training: QA staff monitors new
	Assurance)	inspector for first 2 inspection days,
		providing on-site training
12	PIH-REAC (Quality	Phase II Training: QA staff monitors
	Assurance)	inspector on 3 rd inspection day which is
		the final exam. QA determines on-site, if
		inspector qualifies for full certification or
		recommends suspension from the
		program
13	PIH-REAC (Inspector	Receives QA determination for Full
	Administration)	Certification (inspector is permitted to
		conduct inspections independently).
		Receives Inspector File from Training.
14	PIH-REAC (UPCS	If recommended for suspension from the
	Inspection Training Team)	program, inspector will be referred to the
	,	Training Team. Inspector Candidate will
		be invited to re-apply 12 months from
		date of final QA.

Uniform Physical Condition Standards Inspector Certification Training

Required Item to be submitted

The following questionnaire must be completed and submitted electronically.

- Go to the following website page: http://www.hud.gov/offices/reac/products/prodpass_iaform.cfm
 Follow the procedures, important notes and reminders.
- Email completed Inspector Assessment Form to: Inspector_Assessment_Form@hud.gov

Cost of training

There are no tuition fees for this training. The inspector candidates are responsible for their own travel/lodging expenses.

Contact Us

For more information, call the REAC's Technical Assistance Center (TAC) at 1 (888) 245-4860 (7:00 AM – 8:30 PM EST)

or email the Inspection Certification Training Team directly:

Inspector_Assessment_Form@hud.gov